



-45 Kpa
Max per pecore e capre
Max for sheep and goats
Max für Schafe und Ziegen
Max pour chèvres et brebis

-50 Kpa
Max per vacche
Max for cows
Max für Kühe
Max pour vaches

0481610 Riduzione per vuotometro
Vacuum gauges reduction
Reduktion für Vakuummeter
Réduction pour vacuomètres



E2

1	0482000
1a	0482010
2	0481850
2a	0481860
3	0481600
3a	0481620

**Vuotometri Milkline
Milkline vacuum gauges
Milkline Vakuummeter
Vacuomètres Milkline**

1/2" - ø 100 mm
Vetro / Glass / Glas / Verre

1/2" - ø 80 mm
Vetro / Glass / Glas / Verre

1/4" - ø 63 mm
Vetro / Glass / Glas / Verre

4	0482005
5	0481800
6	0481630

**Vuotometri
Vacuum gauges
Vakuummeter
Vacuomètres**

1/2" - ø 100 mm

1/2" - ø 80 mm

1/4" - ø 63 mm

**Valori di livello di vuoto consigliato / Recommended vacuum levels
Empfohlene Vakuumniveaus / Niveaux conseillés pour le vide**

Impianti a secchio e a trasporto latte / Buckets assembly parlours and pipeline milking plants Eimer und Rohrmelkanlagen / Installations a pots-trayeurs et transferts de lait	-50 [kPa]
Sale di mungitura / Milking parlours Melkstände / Salles de traite	
(Linea alta) - (High line) - (Hochliegende Leitung) - (Ligne haute)	-50 [kPa]
(Linea bassa) - (Low line) - (Tiefliegende Leitung) - (Ligne basse)	-47 [kPa]
Impianti per pecore e capre / Milking plants for sheep and goats Melkanlagen für schafe und ziegen / Installations pour brebis et chevres	38 / -42 [kPa]